

U BOLTS

			<b><i>U BOLTS</i></b>		
1325	<b><i>A</i></b>	<i>sq</i>	1/2 x 4 1/8 x 4"		
13262	<b><i>B-1</i></b>	<i>rnd</i>	3/8 x 1 3/4 x 2 3/4"		
1326	<b><i>B</i></b>	<i>rnd</i>	3/8 x 1 3/4 x 4 3/16"		
1327	<b><i>C</i></b>	<i>sq</i>	3/8 x 1 9/16 x 2 5/8"		
1328	<b><i>D</i></b>	<i>sq</i>	3/8 x 1 3/4 x 4 1/2"		
1329	<b><i>D-1</i></b>	<i>sq</i>	3/8 x 1 3/4 x 5 1/2"		
1330	<b><i>E</i></b>	<i>sq</i>	3/8 x 2 1/16 x 3 3/8"		
1331	<b><i>F</i></b>	<i>sq</i>	3/8 x 2 1/16 x 4 3/8"		
1332	<b><i>G</i></b>	<i>sq</i>	3/8 x 2 1/16 x 5 3/8"		
1333	<b><i>G-1</i></b>	<i>sq</i>	3/8 x 2 3/16 x 7 7/8"		
1335	<b><i>J</i></b>	<i>sq</i>	1/2 x 2 1/16 x 4 1/4"		
1340	<b><i>K</i></b>	<i>sq</i>	1/2 x 2 1/16 x 5 1/2"		
1342	<b><i>L</i></b>	<i>sq</i>	1/2 x 2 1/16 x 6 5/16"		
1343	<b><i>L-1</i></b>	<i>sq</i>	1/2 x 2 1/16 x 7 5/16"		
1344	<b><i>M</i></b>	<i>sq</i>	1/2 x 2 1/4 x 5 1/2"		
1345	<b><i>N</i></b>	<i>sq</i>	1/2 x 3 1/16 x 4 13/16"		
1346	<b><i>O</i></b>	<i>sq</i>	1/2 x 3 1/16 x 5 5/16"		
1347	<b><i>O-1</i></b>	<i>sq</i>	1/2 x 3 1/16 x 6 5/16"		
1348	<b><i>P</i></b>	<i>sq</i>	1/2 x 3 3/8 x 5 1/4"		
1349	<b><i>Q</i></b>	<i>sq</i>	1/2 x 3 3/8 x 6 3/16"		
1350	<b><i>R</i></b>	<i>sq</i>	1/2 x 3 1/16 x 3 5/16"		
1355	<b><i>S</i></b>	<i>sq</i>	1/2 x 4 1/16 x 2 13/16"		
1357	<b><i>T</i></b>	<i>sq</i>	1/2 x 2 5/8 x 3 3/8"		
1358	<b><i>U</i></b>	<i>rnd</i>	1/2 x 2 1/16 x 5"		
1359	<b><i>V</i></b>	<i>rnd</i>	1/2 x 2 3/8 x 5 3/8"		
1360	<b><i>W</i></b>	<i>sq</i>	1/2 x 3 1/16 x 9"		
1300A	<b><i>Y</i></b>	<i>sq</i>	1/2 x 4 7/4 x 8 1/4"		
1361	<b><i>X</i></b>	<i>sq</i>	3/8 x 3 1/16 x 3 7/8"		
1327ss	<b><i>C ss</i></b>	<i>sq</i>	3/8 x 1 9/16 x 2 5/8"		
1335ss	<b><i>J ss</i></b>	<i>sq</i>	1/2 x 2 1/16 x 4 5/16"		
1340ss	<b><i>K ss</i></b>	<i>sq</i>	1/2 x 2 1/16 x 5 5/16"		
1345ss	<b><i>N ss</i></b>	<i>sq</i>	1/2 x 3 1/16 x 4 5/16"		
1347ss	<b><i>O-1 ss</i></b>	<i>sq</i>	1/2 x 3 1/16 x 6 5/16"		